

KAISER-FRONTIER MIDSTREAM, LLC

P.O. BOX 21468 TULSA, OKLAHOMA 74121-1468

6733 South Yale Avenue, 74136
(918) 491-4440

October 30, 2019

RECEIVED

NOV 13 2019

Enforcement and Compliance
Assurance Division

US EPA, Region 8
Environmental Protection Agency
Compliance Assurance and Enforcement Division
1595 Wynkoop St.
Denver, CO 80202-1129

Stationary Source Compliance Program Manager
Air Quality Division
122 West 25th Street
Cheyenne, Wyoming 82002

Re: Kaiser Frontier Mid-Stream, LLC
NSPS OOOO Annual Report (8/3/2018 – 8/2/2019)

Dear Sir or Madam:

Kaiser Frontier Mid-Stream, LLC (KFMS) currently owns and operates the Silo Gas Plant, located in Laramie County, Wyoming. Three reciprocating compressors located at the Silo Gas Plant are affected facilities as identified in §60.5365 of 40 Code of Federal Regulations Part 60 Subpart OOOO, Standards of Performance for Crude Oil and Natural Gas Production, Transmission and Distribution for which Construction, Modification or Reconstruction Commenced after August 23, 2011, and on or before September 18, 2015. With this submittal, KFMS is providing the requisite information and satisfying the annual reporting requirements specified in §60.5420(b) for the compliance period between 8/3/2018 – 8/2/2019 (the Reporting Period).

I hereby certify based on information and belief formed after reasonable inquiry, the statements and information in this Annual Report dated October 30, 2019 are true, accurate, and complete. Should you or members of your staff have any questions or require additional information, please contact Jonathan Baugh at (918) 491-4227.

Sincerely,
Kaiser Frontier Mid-Stream, LLC

By: 
Charles Lock – EHS Manager

Enclosure

List of Affected Facilities - NSPS Subpart OOOO

§60.5420(b)(1)(ii)

API Number	Facility/Well Name	Address or Description of Site Location and Lat./Long. coordinates	Affected Facility Type(s) <i>(Place an 'X' in Every Column That Applies)</i>				
			Gas Well	Storage Vessel	Reciprocating Compressor	Centrifugal Compressor	Pneumatics
N/A	Silo Gas Plant	Laramie County, WY (b) (9)			X		

Reciprocating Compressor Affected Facilities - NSPS Subpart OOOO

§60.5420(b)(4)

Facility Name	Equipment ID	Operations Tracking 60.5420(b)(4)(i)					Deviations To Report? (If Deviations Occurred Put an 'X'. If not leave blank)
		How are you tracking Operations? (Hours or Months)	Actual Time Reported	What is the start date?	What determined start date? (startup, October 15, 2012, or rod packing replacement whichever is later)	Comments	
Silo Gas Plant	C-5010	Months	56	12/15/2014	Initial startup	C-5010	X
Silo Gas Plant	C-5020	Months	12	8/1/2018	Rod packing replacement	C-5020	
Silo Gas Plant	C-5060	Months	15	5/1/2018	Rod packing replacement	C-5060	

Deviations - NSPS Subpart OOOO

§60.5420(b)(2-4)(ii); (5-6)(iii)

API Number	Facility Name/ Well Name	Equipment ID	Start Date	Start Time	End Date	End Time	Explanation
N/A	Silo Gas Plant	C-5010	12/15/2014	N/A	N/A	N/A	Rod packing replacement exceeded 36 months. Replacement will be completed as soon as possible.